

Date 24/10/2024

No.C 0075

customer name Razel Chimes اسم العميل:

Address \Tel: Riyadh - Rawabek العنوان والتليفون:

Description Cooling Issues MFR: Haier

Model No: HXC 118 Serial No: BE691EBA000EKB001 Volt: 220V

Pre-installation	☐	Warranty Service	☐	Service Contract	☒	Service	☒
Installation	☐	Others	☐	Delivery Note	☒		

Service Requested \ Fault Reported: Symptoms of Compressor Failure

Description of Work Performed: New Compressor Installation

* New compressor sourced, matching the model and specifications of old one.
* After the replacement, the refrigerator was plugged and monitored 24 hours.

JOB COMPLETED: YES ☒ NO ☐

Parts Used\Needed:

Part No.	Description	Qty.	Unit Price	TOTAL
AHYCC	Compressor	①	1400	1400
/	/	/	/	/

Duration of Service:

Date	Working Hours	Date	Working Hours
/	/	/	/
/	/	/	/

Labour Hours: Service Charges: 1400 SR.

Customer s Comments: ملاحظات العميل:

Customer s Name: Engineer s Name: Alaa Al-Asyoud

Signature: Stamp Signature: 